

6/21/06

170541



**TABLE 1**  
**SAMPLE DESCRIPTIONS**  
**VIP CLEANERS SITE**

Address	Sample Location	Sample Type	Sample #	Canister #	Valve #	Tetrachloroethene (uG/m <sup>3</sup> )	Trichloroethene (uG/m <sup>3</sup> )	Cis-DCE (uG/m <sup>3</sup> )	Trans-DCE (uG/m <sup>3</sup> )
N/A	N/A	Trip Blank	TB-01	33965	102-07	40	ND	ND	ND
24 Pine St.	NW side of basement	Sub-slab	24Pine	04568	54-10	ND	ND	ND	ND
48/50 Pine St.	Center	Sub-slab	48Pine	11882	103-80	16	ND	ND	ND
	NW side	Sub-slab	50Pine	33571	103-29	13	ND	ND	ND
95 Morris St. Auto Concepts	Basement with heater	Sub-slab	95MorrisA	14885	54-07	ND	ND	ND	ND
	SW corner of back room	Sub-slab	95MorrisB	34730	03-71	510	ND	ND	ND
105 Morris St. Morristown Tire Company	SE basement	Sub-slab	105MorrisA	34440	102-02	8.0	4.8	ND	ND
	South/center of back room	Sub-slab	105MorrisB	34028	03-20	250	23	ND	ND
73 Morris St. Morristown Diner	East/center of basement	Sub-slab	73Morris	23886	62-02	6800	170	ND	ND
44 Pine St.	SE side of basement	Sub-slab	44Pine	4324	103-77	10	ND	ND	ND

**TABLE 1 - Continued  
SAMPLE DESCRIPTIONS  
VIP CLEANERS SITE**

Address	Sample Location	Sample Type	Sample #	Canister #	Valve #	Tetrachloroethene (uG/m <sup>3</sup> )	Trichloroethene (uG/m <sup>3</sup> )	Cis-DCE (uG/m <sup>3</sup> )	Trans-DCE (uG/m <sup>3</sup> )
40 Pine St. Future Day Care Cent	NW corner of back room	Sub-slab	40Pine1	32109	100-034T	2.6	ND	ND	ND
	Duplicate of 40Pine1	Sub-slab	40Pine1B	05712	03-19T	ND	ND	ND	ND
	Center of back room	Sub-slab	40Pine2	34328	100-12	2.6	ND	ND	ND
	South/center at entrance to back room	Sub-slab	40Pine3	13853	95-81	2.5	ND	ND	ND
	SE corner in front room	Sub-slab	40Pine4	33568	103-24	ND	ND	ND	ND
	Backyard	Ambient	40PineA	2387	03-10	4.7	ND	ND	ND
N/A 4A Wilmot Former Kid Fit; Main Building	N/A	Trip Blank	TB-02	23887	103-21	ND	ND	ND	ND
	West port	Sub-slab	4AWil1	34125	100-81	13000	220	31	ND
	East port	Sub-slab	4AWil2	35172	103-84	45000	2700	12000	160
	Duplicate of 4AWil2	Sub-slab	4AWil2B	34475	03-34	44000	2700	12000	160
	Center/east near cracks	Indoor Air	4AWilIA	34453	03-38	220	3.0	8.6	ND
	Duplicate of 4AWilIA	Indoor Air	4AWilIA2	4084	03-25	200	2.8	7.4	ND
4B Wilmot Elite Photography Main Building	Center, port in office	Sub-slab	4BWil	35154	95-01	45000	1100	160	ND
	Center/north on table	Indoor Air	4BWilIA	13999	101-03	170	4.4	16	ND

**TABLE 1 - Continued  
SAMPLE DESCRIPTIONS  
VIP CLEANERS SITE**

Address	Sample Location	Sample Type	Sample #	Canister #	Valve #	Tetrachloroethene (uG/m <sup>3</sup> )	Trichloroethene (uG/m <sup>3</sup> )	Cis-DCE (uG/m <sup>3</sup> )	Trans-DCE (uG/m <sup>3</sup> )
4C Wilmot Cardio-Care Main Building	NE corner port	Sub-slab	4CWil	33881	103-52	42	ND	ND	ND
	SE corner on table	Indoor Air	4CWillA	02330	102-01	36	0.66	0.56	ND
4D Wilmot Amici Hair Design Main Building	East side, port in back room	Sub-slab	4DWil	4191	95-01	1700	58		ND
	East side, near port on box	Indoor Air	4DWillA	9940	101-03	19	0.36	0.18	ND
4E Wilmot Curves Main Building	SW corner port below carpet	Sub-slab	4EWil	34399	102-19	52	ND	ND	ND
	NE in changing area	Indoor Air	4EWillA	39426	103-28	8.6	0.18	ND	ND
8 Wilmot Former Florist Main Building	SW corner port	Sub-slab	8Wil1	05359	03-64	6	ND	ND	ND
	NE corner port	Sub-slab	8Wil2	34318	103-62	8300	57	ND	ND
	SE corner, on floor	Indoor Air	8WillA	21077	55-41	7.2	ND	ND	ND
63 Morris St. Asahi Sushi	SE corner, port near back door	Sub-slab	63Morris	13843	54-08	17	ND	ND	ND

**TABLE 1 - Continued**

**SAMPLE DESCRIPTIONS  
VIP CLEANERS SITE**

Address	Sample Location	Sample Type	Sample #	Canister #	Valve #	Tetrachloroethene (uG/m <sup>3</sup> )	Trichloroethene (uG/m <sup>3</sup> )	Cis-DCE (uG/m <sup>3</sup> )	Trans-DCE (uG/m <sup>3</sup> )
89 Morris St. New Image Cleaners & Tailoring Main Building	Lower floor port on W side	Sub-slab	89Morris1	23997	04-01	42000	730	79	ND
	NE side port in small room	Sub-slab	89Morris2	915	03-05	470	14	ND	ND
	N port behind counter	Sub-slab	89Morris3	912	58-71	690	4.1	ND	ND
Empty Storefront NW side of Main Building	N/center port	Sub-slab	EO1	902	53-45	3000	ND	ND	ND
	SE port	Sub-slab	EO2	34746	05-18	3400	120	9.4	ND
	Center, between rooms	Indoor Air	EOIA	9403	103-57	59	0.40	ND	ND
Ambient 6 Wilmot State Farm Insurance Main Building	South of former florist	Ambient	MorrisA	34373	100-02	1.9	ND	ND	ND
	SE, port in closet	Sub-slab	6Wil	13655	03-73	29000	830	410	ND
	East side on table	Indoor Air	6WillA	14038	96-03	13	0.26	ND	ND
26 Pine St.	Port in center of basement	Sub-slab	26Pine	24484	58-89	10	ND	ND	ND